INDEX

A

Accelerated cooling, 233, 235, 236
Acetelene-oxy welding, 253
Acid electric furnace, 160, 183
  open-hearth, 7, 16, 113
    bottom, 124
    cost of steel, 19
    flexibility, 14
    melting, 129, 166
    quality of steel, 10, 115
    raw material, 28, 159, 161
    typical heats, 137
  vs. basic steel, 10
Air in Bessemer converter, 11, 66, 72, 74, 84, 93
  cooling, 224, 233, 235, 244
  furnace for melting recarburizers, 81, 103
Alternating stress test, 244
Alloy steels, Bessemer, 108
  crucible, 55, 59, 65
  open-hearth, 166
  remelting in electric furnace, 171, 187, 190
Alpha iron, 225
Alumina in acid open-hearth slags, 137
Aluminum, 107, 196
Analysis, control of, in crucibles, 54
Annealing, control of temperature in, 249
  effect on microstructure, 232
  on stresses, 220
  furnaces, 248
  general rules for, 235
Anthracite—as fuel for crucible melting, 40, 50
Applications of electric furnace in foundry, 187
Arc-electric welding, 253
  furnaces, 173
Ash in coke, 98
Ashes, removing, from producers, 46, 126
Austenite, 224

B

Basic vs. acid steel, 10
  Bessemer, 110
  open-hearth, 7, 113
    bottom, 125
    costs of steel, 18
    flexibility, 14
    melting, 146
    quality of steel, 10, 115
    raw material, 28, 161
    typical heats, 149
Bauxite in acid open-hearth slags, 137
Belaiew on microstructure, 229
Bending castings, 252
  test, 240
Bessemer, Sir Henry, 66
Bessemer, basic process, 110
  converter to supply electric furnace, 193
  -electric process, 78, 195
  process, 7, 66
    advantages of, for foundries, 69
    basic, 110
    blowing, 84, 92
    converters, 71
    cost of installation, 30, 69
      of steel, 20, 69
    flexibility, 13, 69
    fuel, 28, 97
    quality of steel, 10, 69, 70
    raw material, 28, 97
    suitability for small work, 15, 16, 69
    tonnage, 26, 70, 96
Beta iron, 225
Blast, in Bessemer process, 11, 66, 72, 74, 84, 93
Blister bar, 34
Blow holes, as starting place for cracks, 246
  from blowing cores, 203
  in badly made open-hearth steel, 136

Blow-holes in Bessemer steel, 16, 66, 87, 106
in crucible steel, 9, 16, 39
in electric steel, 9
influence of venting on, 202
of composition on, 106
of high manganese on, 87, 106
of sink heads on, 204
of size and intricacy on, 16
of special deoxidizers on, 106, 136, 196
of wet moulds on, 202
welding up, 253
Blowing, bottom-blown Bessemer, 84
cores, 203
side-blown Bessemer, 92
Boil, in side-blown Bessemer, 93, 94
Boiler plate scrap, 6, 9, 24, 28, 36, 52, 63, 97
Boiling, of open-hearth bath, 114, 127, 129, 135
Boil-over, of open-hearth bath, 134
Bottom-blown Bessemer vessel, 66, 71
blowing, Bessemer process, 84
making, acid open-hearth, 124
basic open-hearth, 125
electric furnace, 172, 181
vs. lip pouring, 57, 215
Bottoms, for Bessemer converters, 71
Boynton, on heat treatment, 247
Breaking off sink heads, 218
Break-outs, in open-hearth, 127
Brittleness, influence of carbon content, 223
on cracking, 219
produced by free ferrite, 239
Building up impurities in steel, 53, 99, 161, 258

C

Calcium-silicon alloy, 107, 197
Campbell on acid open-hearth slags, 131
tilting open-hearth furnace, 121
Capital needed to build a shop, 29
Carbon, absorption from charcoal in crucibles, 6, 34, 55
from graphite in crucibles, 54
elimination of, in Bessemer converter, 7, 66, 84, 92
Carbon elimination in open-hearth, 7, 113, 134, 145
gains and losses of, in steel making, 196
in acid electric furnace, 184
in cementite, 223
in directly produced iron, 33
in electric furnace, 184, 185, 187, 188
in eutectoid steel, 223
in recarburizers, 103, 166
-iron diagram, 225
loss of, in clay pots, 54
ladles to promote uniformity of, in crucible steel making, 56
low, difficulty of making in crucibles, 39, 42
of pouring sound steel, 106
reaction with FeO in side-blown Bessemer, 94
Carbonic oxide, combustion of, in Bessemer, 66, 85, 90, 94
formation of, in open-hearth, 114
Carr, on cost of installation of open-hearth, 19, 20
open-hearth furnace, 16, 157
Cementation of charcoal iron, 33
furnace, 34
Cementite, 223
Chambers, regenerative, 43, 113
Charcoal, as raw material, 6, 28, 34 52, 54
iron, see "iron charcoal"
use of, on sink heads, 209
Charges—typical. Acid open-hearth, 137
basic open-hearth, 149
crucible, 58
cupola, Bessemer, 100
Charging the cupola, 83
machine, 122
the open-hearth furnace, 122, 132, 147
Checkers, 43, 113
Chemical laboratories, 255
Chills, 208
Choice of a process, considerations governing, 6

Chrome, gains and losses of, in steel making, 109, 168, 196
ore, in basic open-hearth, 125
for patching, 126
steel, Bessemer, 108
crucible, 55, 51, 65
heat treatment, 247
open-hearth, 168
Clay, 202
brick, 40, 44
-lined pots, 49, 54
pots, 41, 49, 54
Cleaning castings, 217
Coal, anthracite, for crucible melting, 40, 50
as fuel 28, 50, 113
as recarburizer, 102, 143, 166
powdered, as fuel, 113
Coke as deoxidizer in electric furnace, 170, 183
in open-hearth, 137
as fuel in Bessemer process, 97
in crucible process, 41, 51
as recarburizer, 102, 166
breeze, in regenerative crucible furnace, 45
-oven gas as fuel, 113
to heat up electric furnace, 181
use of in remelting scrap in open-hearth, 29, 165
Competition, 30
Composition, effect on soundness, 87, 106, 107
Cone, on heat treatment, 237
Continuous melting in open-hearth, 158, 163
Contraction of steel in cooling, 204
Control of analysis, in crucibles, 54
of temperature, in Bessemer, 84, 87, 88
in crucible furnace, 48, 50, 56
in heat treatment, 249
in open-hearth, 132
Converter, Bessemer, 7, 66, 68, 71, 74
bottom-blown, 68, 71
side-blown, 68, 74
Cooling, accelerated, 233, 235, 236
air, 233, 235, 244
Bessemer blows, 87, 95
Cooling castings, 217
curves, 224
oil, 235
water, 232, 235
Copper, in Bessemer steel, 97, 99
in pig iron, 97
Cores, 203
Cornwall pig iron, 97
Cort, 35
Costs of installation, 30
of steel, Bessemer and electric, 194
various processes, 17, 26
Coupons, test, 256
Cracks, from rough usage, 219
hot, 204
Critical points, 224
Crucibles 41, 49, 54
furnaces, 40
for melting recarburizers, 81, 103,
packing, 58
process, 6, 33
advantages for foundries, 39
control of analysis in, 54
cost of installation, 30
of steel, 24
flexibility of, 13, 39
fuel, 28, 40, 42, 43, 50
melting, 50
quality of steel, 9, 35
raw material, 28, 52
suitability for small work, 14, 39
tonnage, 26
use of ladles to promote uniformity, 56
Cupola, charges, for Bessemer work, 99
charging the, 83
for recarburizers, 81, 103
for pre-melting electric furnace metal, 185, 188
open-hearth metal, 159, 165
handling the, 83
placing in Bessemer shops, 80, 81
metal, as recarburizer, 80, 102, 167

D

Dead melting, 36, 55
Dendritic freezing, 227

Deoxidation in acid open-hearth, 135
in basic open-hearth, 148, 149
in Bessemer, 86, 106, 109
influence of temperature, 85
French method of, in acid open-hearth, 136
Deoxidizers, special, 107, 136, 196
Diffusion of carbon, in annealing, 231
in side-blown Bessemer, 94
Digging out castings, 217
Dolomite in basic Bessemer, 110
open-hearth, 125
Door frames, water-cooled, 117
Doors, in open-hearth furnace, 118
Drop bottom converter, 76
test, 238, 241, 242
Dry door frames, 17
sand, 202
Drying out crucible furnace, 47
ladles, 41, 82, 108
open-hearth, 123

E

Elastic limit, 240
Electric furnace, applications of, in foundry work, 187
for melting recarburizers, 81, 103
ferromanganese, 109
Girod, 176
Gronwall, 176
Heroult, 175
induction, 178
Keller, 176
Kjellin, 178
Nathusius, 176
resistance, 178
Röchling-Rodenhauser, 178
Stassano, 174
with open-hearth, 158 188
with Bessemer, 189, 193
process 7, 170
acid, 160, 183
cost of installation, 30
of steel, 22, 23, 194
flexibility, 13, 172
fuel, 28
melting, 182
Electric furnace, process, quality of steel, 9, 170
raw material, 28, 186
setting the bottom, 181
suitability for small work, 14, 172
tonnage, 26
steel, heat treatment, 234
welding, 253
Elongation, 240
Endurance test, 244
Eutectoid, 223
Expansion of open-hearth roof, 124

F

Facing, 202
Ferrite, 223
free, effect on toughness, 239
Ferro-alloys, addition to crucibles, 36, 51, 54
Ferrochrome, 55, 61, 65, 108, 168
Ferromanganese as source of phosphorus, 99
in Bessemer work, 102
in crucibles, 36, 52, 54
in electric furnace, 182
in open-hearth, 136, 149
melting, 102, 109
Ferromolybdenum, 169
Ferrosilicon, in Bessemer work, 88, 91 95, 102
in crucibles, 36, 52, 54
in electric furnace, 182
in open-hearth, 136, 149
melting with scrap for Bessemer, 29, 101
Ferrotitanium, 197
Ferrotungsten, 169
Final flame, 94
Flame, Bessemer, 84, 93
Flexibility, relative, of processes, 12
Fluid pressure, 204
Fluidity of slag, decreased by loam, 128
effect on elimination, 91
influence of MnO, 72, 91
promoted by limestone, 128
Fluorspar, in basic open-hearth, 148
in electric furnace, 182

Forgings, improvement of, by heat treatment, 246
Foundry, departments of, 6
function of, 1
jobbing, 2
specialty, 3
tonnage, 1
use of electric furnace in, 187
Fracture of steel, 222
Fremont testing machine, 238
Freeze-up, of open-hearth bath, 136
Freezing, dendritic 227
French method of deoxidizing, open-hearth, 136
Frequency, of alternating current, 177, 180
Fuel, Bessemer, 28, 97
crucible, 28, 40, 41, 42, 43
different processes, 28
open-hearth, 28, 113
Furnace, annealing, 248
Carr, open-hearth, 16, 157
cementation, 34
crucible, coal, 40
coke, 41
Krupp, 48
oil 42,
Siemens regenerative, 43
advantages of, 48
starting up, 47
electric, applications of, in foundry, 187
for melting ferromanganese, 103, 109
recarburizers, 81, 103
Girod, 176
Gronwall, 176
Heroult, 175
induction, 178
Keller, 176
Kjellin, 178
Nathusius, 176
resistance, 178
Röchling-Rodenhauser, 178
Stassano, 174
with Bessemer, 189, 193
with open hearth, 158, 188
open-hearth, 116
electric, 189
Furnace, open-hearth, starting, 123
tilting, 121

G

Gains and losses of metalloids in steel making, 196
Gamma iron, 225
Gas, coke-oven, for open hearth, 113
natural, for annealing furnaces, 248
for crucible furnaces, 28, 43
for open-hearth furnaces, 28, 113
producer, for annealing furnaces, 248
for crucible furnaces, 28, 43
for open-hearth furnaces, 28, 113
firing the open hearth with, 132
producers for regenerative furnaces, 45
starting up, 47
Gating, 209
German Bessemer practice, 92
Girod electric furnace, 176
Graphite pots, 49
Green sand, 202
Greene's process, 185

H

Hadfield, use of ferro-alloys in Bessemer, 88
Hard coal, see "anthracite"
steel, see "high carbon steel"
tap, 128
Hardening of welds, 254
power of steel, 225
Head, of open-hearth furnace, 120
Heads, sink, 204
Heat losses, in Bessemer gases, 90
treatment, 220
effect on endurance tests, 243
of alloy steels, 247
value of, 238
Heating up Bessemer converter, 73, 77
castings to straighten, 252

Hering, electric furnace, 180
Heroult, electric furnace, 175
Heterogeneity, 227
of crucible steel, 56
Hibbard, on slag inclusions, 197
High carbon steel, bending, 252
heat treatment, 247
in Bessemer, 108
in open-hearth, 166
Hot blast for Bessemer vessel, 77
cracks, 204
Howe, on microstructure, 229
on piping and segregation, 208
on shock test, 238, 246
Huntsman, 34
Hyper-eutectoid steel, 223
Hypo-eutectoid steel, 223

I

Impact test, 238
Increase of impurities, in open-hearth, 161
in Bessemer, 97
in crucible, 52
in steel in general, 258
Induction electric furnace, 178
Ingotism, 230
Intermittent operation, influence on choice of process, 31
International Association for Testing Materials, 226
Intricacy of castings, influence on choice of process, 14
Iron, alpha, 225
beta, 225
charcoal, 28, 33, 52
gamma, 225
pig, 7, 28, 33, 66, 84, 87, 97, 102, 111, 113, 129, 146, 161, 166, 187, 193
as recarburizer, 102, 149, 166
puddled, 6, 9, 28, 36, 52, 161
quality of, 36
Wälloon, 33
wrought, see "iron charcoal," "iron puddled"
carbon diagram, 225
Iron ore in open-hearth, 113, 114, 130 135, 146, 148
in electric furnace, 170, 182

J

Jameson on increase of impurities, 98, 258
Jobbing foundry, 2

K

Killing, 36, 55
Knocking off sink heads, 218
Krupp crucible furnace, 48
Kjellin electric furnace, 178

L

Labor, availability of, influence on choice of process, 31
for Bessemer, 21, 22, 73
for crucible, 24, 25, 41, 42, 47
for electric furnace, 22, 23
for open-hearth, 18, 121
Laboratories, necessity of, 255
Ladles, 198
use of, to promote uniformity of crucible steel, 56
Lag, 224
Lash process, 29, 165
Lay-out of Bessemer shop, 78
of crucible shop, 41, 46
of open-hearth, 122
Lebanon iron, 97
Le-Chatelier on heat treatment, 239
Lègenisel, Walrand process, 88
Lime, in basic open-hearth, 146
in crucibles, 58
in electric furnace, 170, 182
Limestone in acid open-hearth, 138
in basic open-hearth, 146
Lining, of Bessemer converters, 71, 76
of ladles, 198
Lip, vs. bottom pouring, 57, 215
Loam, in acid open-hearth slag, 137, 138
Loss of heat, in Bessemer gases, 90
Losses and gains of metalloids in steel making, 196

Low carbon steel, heat treatment, 239, 241
in crucibles, 39, 42
soundness of, 106

M

Magnesite in basic open-hearth, 125
Magnetism, loss of, in heating, 226
Magnets, for handling raw material, 82, 123
Manganese, effect of high, in bottom-blown Bessemer, 90
in side-blown Bessemer, 95
on heat treatment, 107, 240
on soundness, 87, 106
gains and losses of, in steel making, 196
in Bessemer, 66, 68, 86, 89, 196
oxide in acid open-hearth slag, 131, 138
in Bessemer slag, 72, 91
in crucible slag, 54, 65
retention of, in basic open-hearth, 146, 149
steel, Bessemer, 109
crucible, 65
electric, 171
heat treatment, 247
open-hearth, 169
sulphide, as nucleus for formation of ferrite, 228
use of, to counteract influence of sulphur, 68
absorption of sulphur, 91
Market, influence on choice of process, 8
Martensite, 224
Martin, 113
Mayari pig iron, 109
Melting, in acid open-hearth, 129
in basic open hearth, 146
in crucibles, 50
in electric furnace, 182
recarburizers, 11, 81, 103, 167, 169
Metallography, 222
Methods of steel making, 6
Microscope, 222
Microstructure, 222, 227, 232
Milwaukee type crucible furnace, 43
Mixer, 67
Molybdenum, gains and losses of, in steel making, 196
steel, Bessemer, 108
crucible, 55, 59
open-hearth, 169
Mother metal, 226
austenite, 227
Moulding, 201
Mushet, 67

N

Nailing moulds, 210
Natural gas for annealing furnaces, 248
for crucible furnaces, 28, 43
for open-hearth, 28, 113
Necks, 205
Net-work structure, 223, 227, 239
Nickel, gain and losses of, in steel making, 196
steel, acid open-hearth, 143, 168
basic open-hearth, 156, 168
Bessemer, 109
crucible, 35, 60, 62, 65
heat treatment, 247
Nozzles, 199
Nozzle vs. lip pouring, 215
Nucleus action of slag or sulphide, 228

O

Oil as fuel, 28, 40, 42, 77, 113, 134, 158, 248
-fired annealing furnace, 248
crucible furnace, 42
open-hearth furnace, 113, 158
melting in Bessemer converter, 77
quenching, 235, 237
Open-hearth furnaces, 116
break-outs, 127
bottom making, 124, 125
repairs, 126
tapping, 128
electric process, 189
process, 7, 113
continuous, 121, 158, 163, 192
cost of installation, 30
of steel, 18, 19

Open-hearth process, flexibility, 14, 115
fuel, 28, 113
melting, 129, 146
quality of steel, 8, 10, 114
raw material, 28, 161
suitability for heavy work, 16, 115
tonnage, 26
typical heats, 140, 151
Ore, iron, in acid open-hearth, 113, 114, 130, 135
in basic open-hearth, 113, 114, 146, 148
in electric furnace, 170, 182, 184
Oxidation, in Bessemer, 11, 85, 94
in crucible, 9, 36
in electric furnace, 38, 170, 182
in open-hearth, 10, 114, 133, 136, 148
Oxy-acetelene welding, 253

P

Pearlite, 223
Phosphorus, gains and losses of, in steel making, 196
in acid open-hearth, 7, 10, 114, 161
in basic open-hearth, 7, 10, 114, 147, 150, 161
Bessemer, 110
in Bessemer, 7, 97, 194
electric, 195
in crucible, 6, 36, 52
in electric furnace, 7, 9, 170, 180, 182, 186
increase of, in remelting scrap, 52, 99, 161, 258
in puddling furnace, 37
Physical properties, effect of heat treatment on, 240, 241, 243
Pig iron, see "iron"
and scrap process, 129
Pinch effect, 180
Piping, 204
Pits, Bessemer, 82
cooling castings in, 217, 221
open-hearth, 122
Plate scrap, 6, 9, 24, 28, 36, 52, 63, 97
Ports, of open-hearth furnace, 117
Pots, 29, 41, 54
packing, 58
Pouring, 15, 56, 96, 214
Powdered coal as fuel, 113
Pressure in fluids, 204
Price of castings, influence on choice of process, 17
Processes of steel making, 6
Producer gas, firing open-hearth with, 132
in annealing furnaces, 248
in crucible furnaces, 28, 43
in open-hearth furnaces, 28, 113
Producers, gas, for crucible furnaces, 45
starting up, 47
Production, see "tonnage"
Protection of iron from oxidation, by metalloids, 38, 85, 114, 131
Puddled iron, see "iron"
Puddling furnace, 10, 37
Pyrometers, 249

Q

Quality of Bessemer steel, 8, 10, 70
of crucible steel, 8, 9, 35
of electric steel, 8, 9, 38, 170
of open-hearth steel, 8, 10, 115
of steel by different processes, 8
Quenching castings, 232, 237, 240, 242

R

Rate of cooling, influence of, on physical properties, 236, 239, 242
Raw material, Bessemer, 28, 97
crucible, 28, 36, 52
different processes, 28
electric, 28, 186
handling, 82, 123
open-hearth, 28, 161
Recalescence, 224
Recarburizer, melting, 11, 81, 103, 167
acid open-hearth, 11, 136
basic open-hearth, 11, 115, 149, 166
Bessemer, 11, 85, 95, 102

Red shortness, 68, 204
Reduction of area, 240
Regenerative furnaces, crucible, 43
open-hearth, 113
Reheating, 236
Repairs to open-hearth furnace, 126
Rephosphorizing, in basic open-hearth, 149, 158
in electric furnace, 180, 182
Resistance electric furnace, 178
Reversing valves, 45, 120
Risers, see "sink heads"
Röchling-Rodenhauser electric furnace, 178
Roof, electric furnace, 173
open-hearth furnace, construction of, 117
expansion of, 124
Runners, 209

S

S. A. M. metal, 197
Sand, mixing, 201
Sawing off sink heads, 218
Scrap, boiler plate, 6, 9, 24, 28, 36, 52, 63, 97
melting without pig in open-hearth, 29, 165
remelting, 52, 97, 109, 130, 162, 168, 171, 180, 185, 187
with ferrosilicon, for Bessemer, 29, 101
use of, to cool Bessemer steel, 87, 95
to deoxidize open-hearth steel, 139
Segregation, 197
Shanking, from ladle or vessel, 15, 216
Shanks, 198, 215
Shock test, 238, 242
Shrinkage of steel, 204
cavities, 204
influence of chills on, 208
of sink heads on, 205
welding up, 253
stresses, 220
Side-blown Bessemer vessel, 68, 74
blowing, 92
Siemens, 113
crucible furnace, 43
Silica brick, 45, 123
Silico-spiegel, 108
Silicon, absorption of, in acid electric furnace, 183
calcium alloy, 107, 197
gains and losses of, in steel making, 196
in acid open-hearth, 113, 130
in basic open-hearth, 113, 146
in bottom-blown Bessemer, 66, 84, 89
in crucible steel, 36, 55
in side-blown Bessemer, 92
Sink heads, 204
removing, 218
Size of castings, influence on choice of a process, 14
Skimming crucible steel, 51
Skin drying, 203
Slag, as nucleus for formation of ferrite, 228
hampers division of heats, 13
in acid open-hearth, 7, 10, 114, 147
electric furnace, 183
in basic Bessemer, 110
open-hearth, 7, 10, 113, 147
in Bessemer, 66, 85, 91, 94
electric, 195
in crucible, 35, 51, 57, 58, 65
in electric furnace, 9, 170, 182
in puddling furnace, 37
influence of fluidity on elimination of, 91, 197
use of, in making bottom, acid open-hearth, 125
basic open-hearth, 126
electric furnace, 181
Sleeve brick for stopper rods, 199
Slopping, of Bessemer vessel, 91, 95
Snelus on *Walrand-Légenisel* process, 88
Snot bar, 128
Soft steel, see "low carbon steel"
Solidification of steel, 226
Sorbite, 224
Special steels, see "alloy steels"

Specialty foundry, 3
Specifications for cast steel, 17
for coke, 98
for gas coal, 161
for raw material, 53, 97, 161, 186
Spiegel, 67, 102
Sprue, see "runner"
Starting, gas producers, 47
open-hearth furnace, 123
Siemens crucible furnace, 47
Stassano electric furnace, 174
Steam in Bessemer blast, 87
Steel making, methods of, 6
Stock converter, 77
Stoppers, 199
Stoughton converter, 76
on heat treatment, 237
on piping and segregation, 208
Straightening castings, 252
Stress test casting, 220
Stresses, relief of, 220
Structure, 222
Sulphide of iron, 68
of manganese, as nucleus for formation of ferrite, 228
formation of, 68
Sulphur, absorption of, from fuel, 36, 50, 52, 91, 97 114, 159 161
counteracted by manganese, 91
effect on cracking, 68, 204
gains and losses of, in steel making, 196
in acid open-hearth, 7, 10, 114, 159, 161
in basic Bessemer, 111
open-hearth, 7, 10, 114, 148
in Bessemer, 7, 68, 97
electric, 195
in crucible steel, 36, 50, 52
in electric steel, 7, 9, 170, 180, 182, 183, 185, 186, 189, 194
increase of, in remelting scrap, 52, 99, 161, 258
influence of, counteracted by manganese, 68
in puddling furnace, 37
Swedish iron, 34

T

Tap hole of open-hearth furnace, 119, 125, 126
Tapping the open-hearth furnace, 128
Temper, 34
Temperature, control of, in Bessemer, 84, 87, 88
in crucible furnace, 48, 50, 56
in heat treatment, 249
in open-hearth furnace, 132
estimating, in open-hearth furnace, 134
for annealing, 231, 235
for hot straightening, 252
for reheating, 236
influence of, on deoxidation, 86
Tensile strength, 240
Test, bending, 240
casting for open-hearth, 134
coupons, 256
drop, 238, 241, 242
endurance, 244
impact, 238
stress, 220
Tilting open-hearth furnace, 121
Titanium, 197
Tonnage, crucible process, 26
Bessemer, 26, 96
different processes, 26
foundry, 1
Transformation, 225, 227
Troostite, 225
Tropenas converter, 74
use of ferrosilicon, 88
Tungsten gains and losses of, in steel making, 196
in Bessemer, 108
in crucible, 55, 59
in open-hearth, 169
Turnings, 132, 134, 147
Tuyères, 71, 74, 76

U

Uniformity, promoting, in crucible steel, 56

V

Valves, reversing, 45, 120
Vanadium, gains and losses of, in steel making, 196
Variability of product, influence on choice of process, 12
Venting, 202

W

Walker open-hearth electric furnace, 189
Wälloon iron, 33
Walrand-Légenisel process, 88
Warming up Bessemer blow, 88, 95
Wash, 197
Washed metal, 6, 34, 52, 87, 161
Wasters, 2
Water cooling, of open-hearth furnace, 117
quenching, 232, 235, 237, 240, 242
Welding, 203, 253
Wellman tilting open-hearth furnace, 121
Widmanstättian structure, 230, 234
Wiping slag off crucibles, 51
Wrought iron, see "iron"

Y

Yard, Bessemer shop, 82
open-hearth shop, 123

127340