

## INDEX.

### A

Abel, Sir F., on carbon and iron, 342, 343.

— on diffusion of carbon, 246.

Ablett, C. A., 740.

Abouchoff works, Compression of ingots at, 889.

Abraham on nickel-chrome steel, 411.

Ac points, 352, 353.

Accumulator, Rateau's heat, 682.

Accumulators, 857, 860, 878, 879.

Acetylene for case-hardening, 250.

Acid open hearth practice, 158.

Acid refractory materials, 232.

Acid Siemens process, 140*a*, *et seq.*

— Charge for soft steel in, 169.

— Elimination of impurities in, 170.

— Reactions in, 168.

Adamson testing machine, 307-309.

Adjusting wedges, 587.

Admiralty, Requirements of, 899.

After-blow, basic Bessemer process, 65, 92.

Agitator, Allen's, 52.

Air blast for converter, 23.

Air furnace, 574.

Aired bars, 244, 245.

Akerman on Bessemer reactions, 79, 82, 83, 86.

Aliquippa works, Talbot process at, 202.

Alkaline salts for desulphurisation, 191.

Allen on nitrogen in steel, 382.

Allen's agitator, 52.

— forging press, 875.

— inclined furnace, 547.

Allotropy, 358.

Alloys, copper-silver, Freezing point curve of, 355.

— copper-silver, Photo-micrographs of, 358.

— Iron-nickel, 403.

— Steel, 393-426.

Alpha,  $\beta$ , and  $\gamma$  forms of iron, 359.

Alternate bending machine, Sankey, 325-327.

Alternating current, 720.

Alternating test machine, Arnold, 324, 325

Alumina, Calcined, for polishing, 453.

Aluminium, Action of, in preventing blow-holes, 386.

— Effect of, on gases in steel, 383, 384.

— Influence of, on segregation, 380, 381.

Aluminium, Use of, in crucible steel, 258.

— — — in making pure iron, 195.

— steel, 393-396.

American bloomery process, 293.

— mill practice, 729, 730, 759, 760, 764,

783, 787.

— producer gas, Analysis of, 134.

— specifications, 491-494, 506-515.

— Steel & Wire Company, Wire mill at, 803.

Ammonia recovery plant, 123.

Ammonium chloride, 920.

Analysis of acid steel, 231.

— Armco iron, 196.

— armour plate, U.S. navy, 289.

— basic materials, 233.

— slags, 189.

— steel, 231.

— Bessemer blow, 85, 87, 88, 90, 93, 96.

— fume, 81.

— slags, 85, 87, 90, 93, 97.

— bone for case-hardening, 249.

— cement bars, 244.

— charred leather for case-hardening, 249.

— chrome ore, 233.

— chrome steel, 398.

— Clapp-Griffiths steel, 72.

— Dinas bricks, 232.

— dolomite, 60, 233.

— firebricks, 553.

— flue gases, 658.

— ganister, 232.

— gas, natural, 139.

— — — producer, 127, 134.

— — — water, 139.

— gases from Bessemer converter, 81, 85.

— hardenite for case-hardening, 249.

— Héroult steel, 269.

— loam sand, 235.

— magnesite, 233.

— moulding composition, 236.

— pig irons, 168, 230.

— Robert steel, 74.

— refractory materials, 232

— silica bricks, 232.

— Swedish Bessemer steel, 71.

— — — Lancashire bars, 244.

— Tungsten steel, 413-420, 425*b*.

— typical steels, 230.

**A**  
 Angles, Rolling of, 612, 615, 618, 756, 758.  
 Annealing, 428.  
 — Effect of, on microstructure, 481, 483.  
 — — — on steel castings, 237-240.  
 Anthracite for rearburisation, 176, 189.  
 Antimony, Influence of, on steel, 377.  
 Anvil blocks, 837, 843.  
 Apparatus, Drop-testing, for axles, 330.  
 — — — tires, 334, 335.  
 Appolo Iron and Steel Company, Continuous mill at, 818, 819.  
 Ar points, 352, 353.  
 Arc furnace, Stassano, 277, 278.  
 Archimedean screw in Wilson producer, 119.  
 Area, Reduction of, 299.  
 Armeo iron, 196.  
 Armour plate, Manufacture of, 284-290.  
 Armour plates, Carburising furnace for, 285, 287.  
 — Cast, 288.  
 — Composition of, 284, 289.  
 — Hardening of, 288.  
 — Krupp-Harveyised, 286.  
 — Mills for, 786.  
 — Presses for, 856, 882.  
 — Steel for, 288, 289.  
 — Varieties of, 284.  
 — Wilson's compound, 289.  
 Arnold, alternating test machine, 324, 325.  
 — on annealing castings, 237-240.  
 — arsenic on steel, 375.  
 — Carbon and magnetic properties, 352.  
 — compression tests, 350.  
 — critical points, 361.  
 — diffusion of carbon, 246.  
 — ductility curve of steel, 348.  
 — etching micro-sections, 454.  
 — micro-chemistry of cementation, 244.  
 — polishing micro-sections, 450.  
 — Sub-carbide theory, 360.  
 — Sulphide of iron in steel, 371.  
 — tensile strength of steel, 346.  
 — Vanadium steel, 420-425b.  
 Arnold and Read, on carbides in steels, 396, 399, 400, 408, 415.  
 — on cement Carbon, 343.  
 — on condition of Carbon in steel, 344.  
 Arrangement of Bessemer shop, 49-52.  
 — of open hearth melting shop, 207-212.  
 Arrest points, 352.  
 Arsenic, Influence of, on steel, 375.  
 Ashley's spinning process, 892.  
 Atkinson gas engine detail, 707.  
 Austenite, 464.  
 Automatic feed for producers, Bildt, 129, 130.  
 — reel, 812.  
 Axles, Bend tests for, 332.  
 — Drop tests for, 329.  
 — Manufacture of steel for, 175.  
 — Photo-micrographs of steel for, 488.  
 — Table of results of drop tests, 331.  
 — Tensile strength of crank, 332.

**B**  
 Babcock & Wilcox boilers, 535, 536, 537, 661, 662, 830.  
 "Back lash," 632, 864.  
 "Back pressure," 668, 669.  
 Bagley reheating furnace, 534.  
 Bagnal, Prices of iron plates made by, 782.  
 Baird and Tatlock's pyrometer, 442.  
 Baker, H. B., on combustion of solid Carbon, 113.  
 Baker, T., on gases in steel, 383, 384.  
 Ball and Wingham on desulphurisation, 191.  
 Ball and socket joint, 744.  
 Band saw, 847, 849.  
 Barelay & Sons, Ltd., Travelling table by, 651.  
 Barff process, The, 933.  
 Barrel hoops, 796, 821.  
 Bars, 600, 601, 602, 603, 638.  
 — Blister, 244-247.  
 — Cement, 244, 245.  
 — Cold-drawn, 762.  
 — Cold-rolled, 762.  
 — Kirkstall, 762.  
 — Reeled, 762.  
 — Rolling of, 578, 594, 600, 638, 818.  
 Barrett and Brown on magnetic properties of Silicon steels, 369.  
 Barrow works, Car casting at, 52.  
 Basic Bessemer practice, Lime in, 92, 93.  
 — Losses in, 102.  
 — Manganese additions in, 102.  
 — Oxide additions in, 103.  
 — Recarburisation in, 67, 102.  
 — Removal of Phosphorus in, 99-101.  
 Basic Bessemer process, 58-68.  
 — Chemistry of, 92.  
 — Curves showing reactions of, 94, 100.  
 — Details of, 65-68.  
 — Lining for converter, 58, 61.  
 — Pig iron for, 92, 230.  
 — Plant, 59, 65.  
 Basic materials, Analysis of, 233.  
 — Preparation of, 59, 60.  
 Basic Siemens practice, 184.  
 — Furnace lining for, 182.  
 — Pig and scrap used for, 186.  
 — Plant and furnaces for, 182, 183.  
 — Production of high Carbon steel in, 189.  
 — Tapping the furnace in, 184.  
 Basic Siemens process, 180.  
 — Chemical changes in, 219, 221, 222.  
 — Yield and consumption of materials in, 220, 223.  
 Basic slag, Iron in, 97, 101.  
 — Phosphoric acid in, 97, 189.  
 Bath, Galvanising, 919.  
 Batho furnace, 180, 181.  
 Bauxite, as a basic material, 184.  
 Beam engines, 666.  
 Beard, T. Wire Mill, 799.  
 Beardmore & Co., Press at, 881.

**B**  
 Beardmore's process for armour-plates, 289.  
 Beau-de-Rochas, Gas engine patent by, 698.  
 Beck illuminator, The, 457.  
 Bedson on American rod rolling, 811.  
 Bedson's Mill, 598, 801, 802, 811.  
 Beilby on amorphous layers in metals, 363.  
 Belgian Mill, 631, 797, 798, 799.  
 Bell, Sir L., washing process, 99, 195.  
 Bell for tube-making, 901.  
 Bell-mouthing, 604.  
 Belloc, on gases in steel, 382.  
 Bench for tube-drawing, 895, 899, 900, 901.  
 — for wire-drawing, 911.  
 Bending test, 492.  
 — Alternate, 324-327.  
 Berry, F., & Sons, Saw by, 756.  
 — Rail straightener by, 763, 764.  
 Berthier on Carbon and Iron, 342.  
 Bertrand-Thiel process, 199-200b.  
 Berzelius on Carbon and iron, 342.  
 Bessemer, Sir H., on crucible steel, 257.  
 — Discovery of process by, 1.  
 — Fluid compression tried by, 387, 888.  
 — Ingots devised by, 39.  
 — Plastic compression tried by, 883.  
 Bessemer blow, Pressure of blast in, 23, 69.  
 — Stages of, 79.  
 Bessemer converter, 6.  
 — Bottom section of, 10-12.  
 — Early types of, 3-5.  
 — Lining for, 8.  
 — Rotating of, 7.  
 Bessemer plant, Cambria Iron Works, 51.  
 — Early English, 49, 50.  
 — Modern, 49-52.  
 — North-Eastern Steel Works, 51.  
 — pit, Arrangement of cranes for, 50.  
 Bessemer practice, 54-57.  
 — American, 86, 87.  
 — Casting ingots, 56.  
 — Disposal of slag, 65.  
 — English, 88, 89.  
 — Final addition to charge, 55.  
 — Manganese used in, 55.  
 — pig-iron, Composition of, 83, 230.  
 — Recarburising in, 55, 56.  
 — Resetting pit, 57.  
 — Scrapping the charge, 54.  
 — Swedish, 84-86.  
 — Taking blowers sample, 66.  
 — Taking pit sample, 57.  
 Bessemer Press, 853.  
 Bessemer process, Chemistry of, 79.  
 — Future development of, 215b.  
 — gases from, Analysis of, 81.  
 — History of, 3.  
 — Labour and other cost of, 214.  
 — steel, 231.  
 — Thermo-chemistry of, 103-111.  
 — Yield in, 214.  
 Bessemer shop, Arrangement of, 49, 50, 51, 52.  
 Bessemer's Works, Forging press at, 875.  
 Beta iron, 359.  
 Bethlehem Works, 632, 784, 800, 855.

**B**  
 Bethlen-Falva Works, 211.  
 "B.G." 793.  
 Bicheroux reheating furnace, 540.  
 Bicycle tubes, 898, 899, 903.  
 Bildt, automatic feed for producers, 129, 130.  
 Billet mills, 752, 753, 754, 814.  
 Billets, 623, 742, 753.  
 Birmingham gauge, 917, 918.  
 Bismuth, Influence of, on steel, 377.  
 "Bitts," 837.  
 Black sheet, 794.  
 Blair's direct steel process, 295.  
 Blast for converters, 23.  
 Blast-furnace gas, 691, 692.  
 — in Middlesbrough, 715.  
 — Use of, 715.  
 Bleckley, patent repeater, 805.  
 Blister bars, 244, 246.  
 — Origin of blisters, 246.  
 Blochairn Works, 744.  
 Block for wire-drawing, 911.  
 "Blocks," 142, 143.  
 — with water coolers, 144.  
 Bloom shears, 747, 748, 749, 750, 751.  
 Blooming. See Cogging.  
 Blooms, 613, 742, 745, 747, 748.  
 Blowers, sample in basic practice, 66.  
 Blowholes, Chemical prevention of, 386.  
 — Effect of Aluminium on, 393.  
 — Mechanical prevention of, 891, 982.  
 Blowing engines for converters, 23.  
 Board of Trade Unit, 721.  
 Bochum's Works, Press at, 860, 878.  
 Bodmer, Invention of tire mill, 769.  
 Boecker's wire rod mill, 805, 806.  
 Boetius reheating furnace, 540.  
 Bogie, 564.  
 Boiler, 661, 830.  
 — Babcock, 661, 662, 830.  
 — Belleville, Tubes for, 898.  
 — Lancashire, 661.  
 — plates, 778, 779, 780, 782, 783.  
 — Stirling, 661, 662.  
 — tubes, 898, 899, 900, 904.  
 Boiling, Cause of, in Siemens process, 163.  
 Bolekow, Vaughan & Co.'s Mill, 763.  
 Bolting rolls, 760.  
 Bone, for case-hardening, 249.  
 Bone and Wheeler, on changes in composition of gas during passage through regenerators, 146.  
 — on use of steam in producers, 134.  
 Bonneville's patent for fluid compression, 888.  
 Booth Bros., Charging machine by, 565.  
 Boron steel, 396.  
 Bottle-neck, 838.  
 Boudouard on gases in steel, 382.  
 Bowling Iron Company, Prices of plates, 782.  
 Box pass, 609, 611.  
 Bramah press, 853.  
 Braune on case hardening, 249.  
 — on Nitrogen in steel, 383.

**B**reakages of crank shafts, 847.  
 — engines, 667, 673.  
 — gearing, 666, 775.  
 — guards, 629, 828.  
 — rolls, 575, 604, 608, 613, 625, 629, 789, 790, 821, 826, 828.  
 — shafts, 841.  
 — spindle, 591.  
 — steam hammers, 743, 847.  
**B**reaker, 590.  
**B**reaking-down mills, 808, 809.  
 — rolls, 760.  
**B**resson, on press and hammer, 881.  
**B**reuer and Schumacher's press, 872, 879.  
**B**ricks, Basic, for linings, 61.  
**B**rinell, experiments on steel, 429.  
 — hardness test, 320.  
 — impact tests, 322.  
**B**ritish mill practice, 829.  
**B**ritish Specifications, 495-505, 506-515.  
**B**rittleness consequent on overheating low Carbon steel, 432.  
**B**roadbent charging machine, 163.  
**B**roadhook, 167.  
**B**roughton Copper Company, Fluid compression at, 883.  
**B**rown, A. B., Hydraulic press, 874.  
**B**rown, J., & Co., Mill, 772.  
**B**rown Hoisting Company, Crane by, 824.  
**B**rown & Sharpe, Wire gauge, 917, 918.  
**B**rown's Mill, 629.  
 "Browning" gun barrels, 933.  
**B**ruelier on rolling metal, 600.  
**B**udd on use of blast-furnace gas, 691.  
**B**uggie, 564.  
**B**undling, 762.  
**B**unt, J., Oil tempering forgings, 437.  
**B**urgess and Aston, iron-copper alloys, Properties of, 377.  
 — iron-nickel alloys, Magnetic properties of, 409.  
 — Silicon, Effect of, on magnetic properties of iron, 369.  
**B**urman, on solubility of Phosphoric acid in slag, 193.  
**B**urnt steel, 527.  
 — Microstructure of, 468.  
**B**urstall, Prof., Gas engine experiments, 696.  
**B**utt-welded tubes, 901, 902.  
**B**utter, A., Kirkstall bars, 762.  
 "B.W.G.," 794, 917, 918.

C

**C**alced dolomite, Analysis of, 233.  
**C**alcium, in Ferro-silicon, 377.  
**C**alcium Chloride, Formation of, in electric furnace, 279.  
 — Effect of, on basic slag, 96.  
 — in Saniter process, 96, 192.  
**C**alculation of efficiency of producer gas, 133.

**C**alderbank Steel Works, Mill at, 686.  
**C**alibrating pyrometer, 441.  
 — Sankey tester, 327.  
 — testing machines, 309, 310.  
**C**alipers, Micrometer, 313.  
**C**allender electric pyrometer, 440.  
**C**alorie, Definition of, 103.  
**C**alorific power of gases, 131.  
**C**alorific value of fuel, Determination of, 554.  
**C**ambria Iron Works, 51, 596, 744, 801, 805, 824.  
**C**ampbell on acid Siemens process, 171, 172.  
 — on action of slag in converter, 82.  
 — on basic Siemens slags, 188.  
 — on Bessemer reactions, 90.  
 — on distribution of heat in Siemens furnace, 558.  
 — on heating of scrap, 168.  
 — on influence of Manganese, 375.  
 — on influence of Phosphorus, 372.  
 — on oxidation of iron, Bessemer blow 106.  
 — on Sulphur, Removal of, in basic Siemens, 191.  
 — on variations in strength of steel bars, 319.  
**C**ampbell furnace, 148.  
**C**ampion, Analyses of metal during working of boiler plate charge, 170.  
 — on etching micro-sections, 454.  
 — on heat treatment, 432, 435.  
**C**apron on fluid compression, 888.  
 — on presses, 880, 881.  
**C**ar-casting, 52, 53.  
**C**ar pusher, 52-54.  
**C**arbide of Calcium, Formation of, in electric furnace, 279.  
**C**arbide of iron, 342.  
**C**arbide of iron and Manganese, 344, 400.  
**C**arbides, Heat of formation of, 108.  
 — in steels, 396, 399, 400, 408, 415.  
**C**arbo-allotropic theory, 360.  
**C**arbon, Cement, 342, 343.  
 — Combination of, with iron, 341, 342.  
 — Combustion of, 112, 113.  
 — condition of, Changes of, 360.  
 — at critical points, 353.  
 — in iron, 342.  
 — in steel, 344.  
 — Diffusion of, in steel, 246.  
 — Effect of, on compression of steel, 350.  
 — on ductility, 348.  
 — on magnetic properties, 351.  
 — on physical properties, 345, 350, 351.  
 — on quenching, 351.  
 — on tensile strength, 346, 516.  
**C**arbonite, 342.  
**C**arbonising, 342, 343.  
 — Hardening, 342, 343.  
 — Oxidation of, in acid Bessemer, 80.  
 — Removal of, in acid Siemens, 170.  
 — in Bessemer blow, 80.  
 — Temper, 343, 344.

**C**arbon Dioxide, Formation of, in Bessemer blow, 106.  
 — in steel, 382, 383, 384.  
 — Specific heat of, 132.  
**C**arbon Monoxide, Calorific power of, 131.  
 — in steel, 382, 383, 384.  
 — Specific heat of, 132.  
 — Use of, for case-hardening, 250.  
**C**arbon Steels, Microstructural composition of, 465, 466.  
 — Photo-micrographs of, 472-479.  
**C**arbonless iron, Hardening of, 362.  
**C**arburising furnace for armour plates, 285, 287.  
**C**arburising materials used in case-hardening, 248.  
**C**arnegie, A., on natural gas, 691.  
**C**arnot, on constitution of pig-iron, 107.  
**C**aron, on Carbon and iron, 342.  
**C**arpenter, on high-speed tool steels, 425b.  
 — on stress theories of hardening, 362-365.  
**C**arville Electric Station, 718.  
**C**ase-hardening, 247-250.  
**C**aspersson, converter ladle, 70.  
**C**ast armour plate, 288.  
**C**ast iron, Expansion of, 789.  
**C**ast steel, 251-260.  
 — Photo-micrographs of, 480-482.  
**C**asting, *in vacuo*, 891.  
**C**asting ingots, 30-38.  
 — Arrangements for, in Bessemer practice, 56.  
 — — in Siemens practice, 207-210.  
 — on cars, 52, 53.  
 — under pressure, 387, 883, *et seq.*  
**C**asting crane, 28, 29, 30.  
**C**asting ladle, 24-28, 164, 165.  
 — on overhead crane, 209.  
**C**asting pit, 38, 49, 50.  
 — Straight in Bessemer practice, 50, 52.  
**C**astings, Steel, 233-240.  
**C**atalan Forge, 293.  
**C**atcher, 598, 636, 638.  
**C**ement, Portland, 932.  
**C**ement bars, 243, 244.  
 — Grading, 244.  
 — Microstructure of, 244, 490.  
 — Photo-micrographs of, 490.  
**C**ement Carbon, 342, 343.  
**C**ementation furnace, 241, 242.  
**C**ementation process, 241-247.  
**C**ementite, 462.  
**C**entrifugal action, 891.  
**C**hanging rolls, 754.  
**C**hannels, 607, 616.  
**C**harging fuel in producers, 129, 130.  
 — heavy ingots, 566.  
 — the open hearth furnace, 159.  
 — reheating furnaces, 562.  
 — small pieces, 568.  
**C**harging furnaces, Horizontally, 547, 548, 562, 563, 564, 565, 566, 567.  
 — Inclined, 547, 548, 571, 572.  
 — Vertically, 534, 561, 568, 569, 570.  
**C**harging machines, 160-163, 562, *et seq.*  
 — Booth's, 565.  
 — Broadbent overhead, 163.  
 — Horizontal, 563, 564, 565, 566, 567.  
 — Lowca Engineering Company's, 563.  
 — Vertical, 567, 568, 569, 570.  
 — Wellman, 15, 161, 565.  
 — Wellman-Seaver, 162, 565, 568, 569.  
**C**harpay, on case-hardening, 250.  
**C**heese ingot moulds, 177-179.  
**C**heeses, 769.  
**C**hemical changes in basic open hearth, 219, 221, 222.  
 — Hoesch process, 217.  
 — Talbot process, 225, 226, 227.  
**C**hemical treatment of feed water, 658.  
**C**hemistry of acid Bessemer process, 79.  
 — of acid Siemens process, 168.  
 — on basic Bessemer process, 92.  
 — of crucible steel process, 257.  
 — of gas producers, 113, 114.  
**C**henot's process, 294.  
**C**hilled rolls, 573, 574, 575, 619, 621, 777, 783, 789.  
**C**himney for Siemens furnace, 155.  
**C**hisel temper, 257.  
**C**hocks, 580-586.  
**C**hrome nickel steel, 410.  
**C**hrome ore, Analysis of, 233.  
 — joint in basic furnace, 182.  
 — lining for basic furnace, 184.  
**C**hrome steel, 396-398.  
**C**hromium, Influence of, on steel, 396.  
 — Oxide, for polishing, 453.  
**C**hurch, W., Vacuum casting, 891.  
**C**lapp-Grieffiths converter, 71.  
**C**lark, D. R., on distribution of heat in reheating furnace, 558.  
**C**lerk, D., Gas engine, 708.  
**C**leveland Rolling Mill Company, 805.  
**C**lose-annealing, 927.  
**C**lot, 167.  
**C**louet, diamond and iron, 341.  
**C**lutch, Reversing, 774, 775, 776.  
**C**oal, 129, 531, 537, 538, 656.  
**C**obalt, Influence of, on steel, 398, 399.  
**C**odnor Park Works, 830.  
**C**ogging, 578, 598, 609, 610, 611, 638, 639, 742, 743, 744, 745, 751.  
 — by hammer, 742, 743, 744, 745, 752.  
 — engines, 674, 746.  
 — mill, 578, 598, 609, 610, 674, 750, 827.  
 — rolls, 575, 578, 610, 827.  
**C**oil clutch, 775.  
**C**oke for producers, 129.  
 "Coke Finish," 930.  
**C**oke-oven gas, 692.  
 — Analysis of, 693.  
 — Calorific power of, 693.  
 — in Middlesbrough district, 715.  
 — Use of, 715.  
**C**olby, on copper in steel, 376.  
**C**old bending tests, 329.  
**C**old gas efficiency, of producers, 132.  
**C**old rolling, 762.

Cold saw, 756, 757.  
 Cold shortness, 2.  
 Cold work, Effect of, 363.  
 "Collaring," 610, 828.  
 Collars on rolls, 592, 593, 609, 610, 622, 624, 625.  
 Colley, J., casting ladle, 28.  
 — on basic bricks, 61.  
 Combination mills, 808.  
 Combined process, Yield and consumption of materials in, 224.  
 Combustion of Carbon, 112, 113.  
 Comparisons, Bessemer and Siemens processes, 213-216.  
 — Electric processes, 280, 281, 282.  
 — English and American practice, 625, 690, 792, 827, 829, 833.  
 — English and Continental practice, 537, 633, 690, 715, 734, 792, 827, 829, 833.  
 — Gas and electric plant and steam and exhaust steam plant, 738.  
 — Hammer and cogging mill, 744, 745.  
 — Hammer and rolling mill, 600, 745, 834, 854.  
 — Heavy and light hammers, 841.  
 — Press and hammer, 879.  
 — Single and double-acting hammers, 842.  
 — Three-high and reversing mill, 639, 641, 764, 827.  
 Composition of gases from converter, 80, 81.  
 — of pig-iron for acid Bessemer, 83.  
 — of water gas, 139.  
 Compound armour plates, Wilson's, 289.  
 — engines, 674, 687, 827, 831.  
 Compounds, Heat of formation of, 105.  
 Compression, Fluid. See *Fluid compression*.  
 — Lateral, 390.  
 Compression tests, 317.  
 — Effect of Carbon on, 350.  
 Condensing engines, 666, 679, 687.  
 Condensing plants, Central, 680.  
 Constituents of steel, Arnold on, 360.  
 — Micro-, 461-465.  
 Constitution of pig-iron, 107, 108.  
 — of steel, 352-365.  
 — of special steels, 365a, 396, 399, 400, 403, 407, 411, 416.  
 Consumption of fuel in crucible melting, 260.  
 — of materials in basic open hearth, 220, 223.  
 — combined process, 224.  
 — Hoesch process, 218.  
 — Talbot process, 227, 229.  
 Continuous mills, 595, 598, 607, 801, 804, 811, 814, 815, 817, 818, 819.  
 Continuous reheating furnaces, 546.  
 Continuous steel process, Talbot's, 200b-203.  
 Continuous wire-drawing, 912.  
 Contraction of area, 299.  
 — of steel when cooling, 523, 525, 821, 838.

Converter, Air blast for, 23, 69, 714.  
 — bottom section, Details of, 9.  
 — Concentric for basic practice, 6, 59.  
 — Core for ramming, 9.  
 — Fixing bottom section to, 62, 64.  
 — for acid process, 6.  
 — fume, Analysis of, 8.  
 — Lime shoot for, 65.  
 — Lining of, 8.  
 — linings, Basic, 61.  
 — Mass action in the, 82.  
 — Materials for lining, 13, 59, 232.  
 — Pressure of blast, 23, 69.  
 — Supply of metal to, 21.  
 Types of, Early, 4, 5.  
 — Hatton, 71, 72.  
 — modern, 6.  
 — Robert, 73.  
 — small, 68-78.  
 — Stock, 78.  
 — Swedish, 69.  
 — Swedish, fixed, 70.  
 — Tropenas, 77.  
 — Walrand-Legenisel, 75.  
 Converting pots, 243.  
 Cooling beds, 818, 820, 822.  
 Copper, Influence of, on steel, 375-377.  
 Copper-silver alloys, compared with iron Carbides, 358.  
 — Freezing point curve of, 355.  
 — Microstructure of, 358.  
 Core for ramming converters, 9.  
 Corliss engine, 690, 830.  
 Corrosion of nickel steel, 410.  
 — Prevention of, 919-933.  
 Corrugated sheets, 919.  
 Cort, Hy., 526, 530, 596, 600.  
 Cost of fuel, 830, 831.  
 Cost of labour, 805, 821, 830.  
 Costs, Comparison as to, in acid and basic processes, 214.  
 — in Bertrand-Thiel process, 215.  
 — in crucible melting, 260.  
 — of electrical smelting of steel, 280-282.  
 — in Héroult process, 269.  
 Cotton ties, 596, 794.  
 Coupling boxes, 576, 590.  
 Cowper-Coles, galvanising process, 925.  
 — Sherrardising process, 925.  
 Cracks in ingots, 392, 393.  
 Cramp-bars, 577, 620.  
 Cranes, Arrangement of, at Bessemer pit, 48.  
 — for centre casting, 28, 29, 30.  
 — "Goliath," 824.  
 Ingots, 38, 39.  
 — for ingot stripping, 166.  
 Receiving, in Bessemer shop, 50.  
 Transfer, 822, 823.  
 Travelling, 822, 823, 824.  
 Crank shaft, 847, 848.  
 Cream separator, 891.  
 Crescent steel, 414.  
 Crewe Works, 526, 598, 638, 769.  
 Critical points, 352, 353.

Critical points, Arnold on, 360, 361.  
 — Brinell on, 429.  
 — Howe on, 352, 361.  
 — Le Chatelier on, 353.  
 — Osmond on, 352, 359.  
 — Sauveur on, 362, 430.  
 "Crocodile," 899.  
 Crop ends, 528, 747, 749, 752, 756, 822.  
 Crossley Bros., Gas engines by, 696.  
 Crucible steel, 251-260.  
 — Chemistry of, 257.  
 — Furnaces for melting, 251, 258, 259, 260.  
 — Grading and treatment of, 256.  
 — Manufacture of, 254.  
 — Precautions necessary during melting, 255.  
 — Temper of, 256.  
 Crucibles, 252, 253.  
 Cryohydrates, Definition of, 354.  
 Crystalline steel, Restoration of, 439.  
 Cubillo, Major, on distribution of heat in puddling furnace, 558.  
 Cupola furance, 14, 15.  
 Current, Kinds of, employed, 720.  
 Curves, showing composition of gas from converter, 80.  
 — influence of Carbon on tensile strength, 347.  
 — oxidation in Bessemer converter, 80, 87, 89, 91.  
 — — in Swedish Bessemer process, 84.  
 — record by Baird and Tatlock pyrometer, 443.  
 — removal of Phosphorus in basic Bessemer, 100.  
 — storages of heat from exhaust steam in a Rateau accumulator, 684.  
 — temperature variations in producer gas, 136.  
 Cutting to length, 747, 752, 756, 757.  
 Cutting tools, 847, 848, 849, 850, 851.  
 Cyanide of potash, for case-hardening, 250.  
 Cylinders, Weldless steel, 898.

D

Daelen, 551, 631, 881.  
 Darby, on changes in composition of gas after passing through regenerators, 146.  
 — on lining basic furnaces, 182, 183.  
 — rebarburing process, 189, 190.  
 Davy, comparison of press and hammer, 880.  
 Davy Bros., patent coupling, 689.  
 — Presses by, 862, 863, 864-869.  
 — Reversing engine by, 678.  
 Dawson, design of Siemens furnace, 141, 142.  
 Dawson gas producer, 121.  
 — Analysis of gas from, 134.  
 Dawson-Robinson-Pope, crucible steel furnace, 259.

Dekin and Johnson, weldless rifle barrels, 902.  
 Defects, Mechanical, Microscopical examination for, 460.  
 Deflection of springs under varying loads, 340.  
 Dellwik-Fleischer water gas, 138.  
 Demange, Comparison of press and hammer, 881.  
 Dephosphorising processes, 195, 197.  
 Desilicising in Bessemer converter, 195.  
 Diamond, Combination of, with iron, 341.  
 "Diamond" pass, 614, 623.  
 Dies for wire-drawing, 915.  
 Dies, Steel for, 257.  
 Diesel oil engine, 696.  
 Differential arrangement of pyrometers, 444.  
 Diffusion of Carbon in steel, 246.  
 Dilatation of iron-nickel alloy, 401.  
 Dillner on copper in steel, 376.  
 Dinas brick, Analysis of, 232.  
 Direct processes of steel manufacture, 291.  
 — 295.  
 — American bloomery process, 293.  
 — Blair's process, 295.  
 — Bloomery process, 291.  
 — Catalan process, 293.  
 — Chenot's process, 294.  
 — Difficulties of, 291.  
 — Eames process, 295.  
 — Siemens process, 295.  
 — Stuckofen process, 294.  
 Dispatching material, 753, 760, 762, 778, 796, 822, 824.  
 Dixon, Prof., explosion of Cyanogen and Oxygen, 113.  
 Dolomite, Analysis of, 60, 233.  
 — as basic material, 184.  
 — Preparation of, 59.  
 "Dolphin," U.S. dispatch boat, Broken shaft in, 841.  
 Dorman, Long & Co., Ltd., Mill, 734.  
 Double-acting hammer, 842.  
 Double-Duo mill, 799.  
 Double shear steel, 245.  
 "Doubles" in sheets, 790, 794.  
 Dowlaids Works, 598, 627, 641, 799.  
 — Mill at, 627, 799.  
 — Rolls at, 641.  
 Draught in chimney, 531.  
 — in rolling, 608, 610, 611, 613, 614, 615, 616, 624, 632, 810, 826.  
 Draw-bench, 895, 899, 900, 901, 911.  
 Drifting test, 328.  
 Drilling at high speeds, 851.  
 Drop tests, 329, 492, 493.  
 — for axles, 496, 497.  
 — for rails, 495, 496.  
 — for tires, 497, 498.  
 Drop-testing machine for axles and rails, 330.  
 — for tires, 334, 335.  
 Dross in zinc baths, 921.  
 Dry galvanising, 925.  
 Dry sand moulds, 236.

Ductility, Influence of Carbon on, 348.  
 Dudley, P. H., on number of passes, 768.  
 Duff gas producer, 121.  
 Dufour, Comparison of press and hammer, 881.  
**Duisberg Machine Company**, Mill by, 799, 800.  
**Duplex process**, 204.  
 — Yield and consumption of material in, 224.  
**Duquesne Works**, Mill at, 754, 821.  
 Durfee, on early rolling mill, 600.  
 Dust-catcher, Siemens furnace, 147.  
 Dyer, Col., on fluid compression, 890.

**E**

**Eames' direct steel process**, 295.  
**Eckhardt's revolving moulds**, 892.  
**Economisers**, 660.  
 "Edging," 602, 609, 611, 623, 783, 818, 829.  
**Edwards**, on hardening of special steels, 364.  
 — on stress theories, 363.  
 — on Tungsten Carbide, 416.  
**Efficiency** of electric transmission, 720.  
 — of gas engines, 695.  
 — of gas producers, 130-136.  
 — of reheating furnaces, Determination of, 554.  
 — of steam engines, 695.  
**Ekman** reheating furnace, 546.  
**Elastic limit**, Definition of, 298.  
 — Determination of, 314.  
 — Modulus of, 298.  
**Electric current**, 720.  
**Electric driving**, Economy of, 736.  
**Electric furnace**, Frick, 263.  
 — Giffre, 277.  
 — Gin, 276.  
 — Girod, 271, 272.  
 — Grönwal, 273, 275.  
 — Héroult, 267-269.  
 — Hiorth, 263.  
 — Induction, 261.  
 — Keller, 270, 271.  
 — Kjellin, 261, 262.  
 — Rochling-Rodenhauser, 264-266.  
 — Ruthenberg, 275.  
 — Stassano, 277, 278.  
**Electric furnaces**, Costs in, 280-282.  
 — Removal of Phosphorus and Sulphur in, 279, 280.  
**Electric processes**, compared, 280-282.  
**Electric smelting** of steel, 261-283.  
**Electric transmission** of power, 719, 720.  
**Electricity**, Public supply of, 736.  
**Electro-magnets** for lifting plates, 780.  
**Electro-plating**, 924, 933.  
 Ellis, armour plate process, 289.  
**Ellis-May process**, 891.  
**Elongation**, Calculation of, 316.  
 — Definition of, 299.

**F**

**Faraday**, on condition of Carbon in iron, 342.  
**Favre and Silbermann**, calorific power of gases, 131.

**Feed water**, Chemical treatment of, 658.  
 — Heating of, 659, 660.  
**Fen**. See *Fins*.  
**Fencing**, Wire for, 833.  
**Ferrite**, 461.  
**Ferro-Managnese**, 399.  
 — Additions of, 67.  
 — — in acid Siemens, 163.  
 — — in basic Bessemer, 101, 102.  
 — Analyses of, 55, 67.  
**Ferro-Silicon**, Action of, 386.  
 — Analyses of, 377.  
 — Calcium in, 377.  
 — Use of, in Walrand process, 75.  
**Ferro-Titanium**, 413.  
**Ferro-Tungsten**, 413.  
**Ferro-Vanadium**, 423.  
**Ferrous oxide in steel**, 386.  
**Ferrous phosphate**, Heat of formation of, 111.  
**Fery radiation pyrometer**, 445.  
**Fielding and Platt**, Forging press by, 874.  
 — Hydraulic shears by, 750.  
 — Tube-staving press by, 905.  
**Finishing metal**, Bessemer process, 55.  
**Finishing temperature**, Effect of, on structure, 489.  
**Finkiner**, Removal of Sulphur in basic blow, 98.  
**Fins**, 602, 603, 604, 608, 610, 612, 614, 617, 622, 625, 811, 907.  
**Firebricks**, Analyses of, 232, 553.  
**Firegrates**, 657.  
**Fire hole**, 251.  
**Firth, T., & Sons**, speedicut steel, 417.  
 — Wire by, 916.  
**Firth Works**, Press at, 882.  
**Fittings** for tubes, 905.  
**Flaked bars**, 244.  
**Flanges** for tubes, 905.  
**Flather**, on self-hardening steels, 416.  
**Flats**, Rolling of, 610, 612, 622, 625, 631, 634, 753.  
**Flow** of solids, 607, 608.  
**Flue gases**, Analysis of, 658.  
**Fluid compression**, Abortive attempts at, 888.  
 — at Abouchoff Works, 889.  
 — Bessemer's experiments, 387, 883, 888.  
 — Bonneville's patent, 888.  
 — Col. Dyer on, 890.  
 — Greenwood on, 889.  
 — Gun Foundry Board (U.S.) on, 890.  
 — Harmet's process, 387, 886, 887.  
 — History of, 883.  
 — Holingrake's proposals, 883.  
 — Introduction of, 883.  
 — Jones' process, 888.  
 — Krupp's experiments in, 888.  
 — Limited use of, 891.  
 — Methods of, 888.  
 — Moulds used in, 885.  
 — Press used for, 885.  
 — Pressure necessary for, 884, 885, 888.

**Fuel, Consumption of,** in Pietzka's furnace, 546.  
 —— in Ponsard's furnace, 541.  
 —— in Price's furnace, 541.  
 —— in reheating furnaces, 560.  
 —— in Siemens' reheating furnace, 538.  
 —— in slack-fired furnace, 534.  
**Fuel, Cost of,** 830, 831.  
 —— Economy of, 678, 679, 687, 831, 833.  
 —— for producers, 129.  
 —— Quality of, 531, 535, 536, 574.  
**"Fuller,"** 600.  
**Fume from converter,** Analysis of, 81.  
**Furnace, Air,** 574.  
 —— Annealing, 534, 895, 915, 927.  
 —— Bar, 791.  
 —— Batho, 180, 181.  
 —— Campbell, 148.  
 —— Carburising, for armour plates, 285, 287.  
 —— Cementation, 241, 242.  
 —— Crucible pot melting, 251.  
 —— gas-fired, 258-260.  
 —— **Electrical,** Frick, 263.  
 —— Giffre, 277.  
 —— Gin, 276.  
 —— Girod, 271, 272.  
 —— Grönwal, 273-275.  
 —— Héroult, 267-269.  
 —— Hiorth, 263.  
 —— Induction, 261.  
 —— Keller, 270, 271.  
 —— Kjellin, 261, 262.  
 —— Rochling-Rodenhauser, 264-266.  
 —— Ruthenberg, 275.  
 —— Stassano, 277, 278.  
 —— Gas-fired, for crucible steel, 258-260.  
 —— Heating, 844.  
 —— **Reheating,** Allen's, 547.  
 —— Bagley's, 534.  
 —— Bicheroux's, 540.  
 —— Boetius', 540.  
 —— Bottoms for, 553.  
 —— Charging of, 534.  
 —— Coal-fired, 531.  
 —— Comparison of various systems, 533, 534, 559, 560.  
 —— Consumption of fuel in. See *Fuel, Consumption of.*  
 —— Continuous, 546.  
 —— Draught in, 531, 534, 535.  
 —— Efficiency of, 554.  
 —— Ekman's, 546.  
 —— for forgings, 878, 879.  
 —— Gas-fired, 537.  
 —— Gorman's, 541.  
 —— "Gravity discharge," 547.  
 —— Hollis', 546.  
 —— Inclined, 546.  
 —— Materials for constructing, 552.  
 —— Methods of working, 533, 543.  
 —— Moor, 534, 560.  
 —— Morgan's, 547.  
 —— Muffle, 835.

**Furnace, Reheating, New form, Siemens',** 541-544.  
 —— Non-reversing, 541.  
 —— Pietzka's, 545.  
 —— Ponsard's, 541.  
 —— Price's, 541.  
 —— Radcliffe's, 541.  
 —— Raising steam with, 534.  
 —— Recuperators for, 541.  
 —— Regenerators for, 540.  
 —— Reversing, 542.  
 —— Siemens', 538, 540.  
 —— Siemens' new form, 541-544.  
 —— Slack-fired, 533.  
 —— Slag from, 531.  
 —— Soaking pits used as, 548.  
 —— Swindell's, 541.  
 —— Talbot's, 547.  
 —— Vertical, 547, 550, 552.  
 —— Waste in, 533, 534, 540, 547, 551, 846.  
 —— Water evaporated by, 535.  
 —— Weardale, 546.  
 —— Reverberatory, 574.  
 —— Siemens' new form, 258, 260.  
 —— old type, 142.  
 —— Tilting, 147-149.  
 —— Wellman, 149.

**G**

**Galloway's, Ltd., Engines by,** 673.  
 —— method of handling reversing engines, 689.  
 —— Press by, 875.  
**Galvanised sheets,** 919, 920, 921.  
**Galvanising, Bath for,** 919.  
 —— Cold processes, 924.  
 —— Cowper-Cole's process, 925.  
 —— Disadvantages of hot process, 924.  
 —— Dross from, 921.  
 —— Dry, 925.  
 —— Electro-deposition of zinc, 924.  
 —— Flux for, 919, 920, 924.  
 —— Heathfield's process, 920.  
 —— Hot, 919, 920, 921.  
 —— Invention of, 919.  
 —— of irregular shapes, 924.  
 —— Machine for, 921, 922, 923.  
 —— Modern process, 919.  
 —— Old dipping process, 923, 924.  
 —— plates for torpedo boats, 925.  
 —— sheets, 919, 920.  
 —— Spent acid from, 926.  
 —— tubes, 924, 925.  
 —— wire, 917.  
**Gamma iron,** 359.  
**Ganister,** Analyses of, 13, 232.  
**Garrett's wire-rod mill,** 803, 804, 805, 811.  
**Gary-steel plant,** 470.  
 —— Millat, 766.  
**Gas, Blast furnace,** 691.  
 —— Cleaning of, 692.  
 —— Coke-oven, 692, 693.

**Gas bottles,** 898.  
**Gas engines, Details of,** 712.  
 —— Development of, 698.  
 —— Efficiency of, 695.  
 —— Governing of, 710.  
 —— Limitations of, 712.  
 —— Starting of, 712.  
**Gas-fired boilers,** 658.  
**Gas-fired crucible furnaces,** 258-260.  
**Gas-fired reheating furnaces,** 537.  
**Gas in fluid steel,** 884, 887, 888.  
**Gas, Natural,** 139, 691.  
**Gas, Producer,** Analyses of, 134.  
 —— Changes in composition of, on passing through regenerators, 146.  
 —— Heating value of, 114.  
 —— Specific heat of, 132.  
 —— Sulphur in, 174.  
 —— Testing of, before use, 158.  
**Gas producers,** 112-129.  
 —— Automatic feed for, 129, 130.  
 —— Charging of, 129.  
 —— Efficiency of, 130-136.  
 —— Calculation of, 133.  
 —— Jenkins's formula for, 131.  
 —— Fuel for, 129.  
 —— Irregularities of working in, 136.  
 —— Mechanical feed for, 120.  
 —— Position of, relative to furnace, 156, 157.  
 —— Reactions in, 113, 114.  
 —— Theory of, 112.  
 —— Types of, 115.  
 —— Dawson, 121.  
 —— Duff, 121.  
 —— Hughes, 126, 127.  
 —— Kerely, 127, 128.  
 —— Mechanical, 124-128.  
 —— Mond, 121-124.  
 —— Rehmann, 128.  
 —— Siemens, 115, 116, 117.  
 —— Talbot, 124, 125, 126.  
 —— Wilson, 117-120.  
 —— Use of lime in, 175.  
 —— Use of steam in, 134, 135.  
 —— Variations in temperature, 136.  
 —— Water, 138.  
**Gas pump,** Humphrey, 713.  
**Gas sampler,** Stead's, 137.  
**Gas strip,** 634, 796.  
**Gas, Water,** 137-139.  
**Gases, Analysis of,** from converter, 81.  
 —— Calorific power of, 131.  
 —— Carbon in, 131.  
 —— Occlusion of, by iron and steel, 382, 386.  
 —— Use of, in case-hardening, 250.  
**Gauge for sheets,** 792, 793.  
 —— for wire, 794, 917.  
 —— "B.G.," 793.  
 —— "B. & S.," 917.  
 —— "B.W.G.," 793, 794, 917.  
 —— "S.W.G.," 917.  
**Gautier** on forging presses, 880, 881.  
**Gearing,** 666, 667, 746.

**H**

**Hadfield,** on Aluminium steel, 394.  
 —— Chrome steel, 397.  
 —— Cobalt steel, 398.  
 —— fuel consumption in crucible melting, 260.  
 —— heat treatment, 289.

**Hadfield**, on influence of Silicon on steel, 365.  
 — Manganese steel, 400, 401, 402.  
 — Nickel steel, 404, 405.  
 — production of sound ingots, 387-390.  
 — Tungsten steel, 417-420.  
**Hall**, J. F., on Nickel steel, 405.  
**Hall reversing valve**, 153.  
**Hall & Searf's patent scraper**, 795.  
**Hallside Steel Works**, Turbines at, 685.  
**Hamilton's Steel and Iron Company**, 752.  
**Hamilton Steel Works**, Casting ingot at, 37.  
**Hammer**, Steam, Advantages of, 835, 854.  
 — and cogging mill compared, 742, 744, 745.  
 — and lathe compared, 847.  
 — and press compared, 843, 853, 854, 880, 881.  
 — and rolling mill compared, 600, 745, 834, 854.  
 — Anvil block for, 837, 843, 880.  
 — Bits for, 837, 846.  
 — Blow struck by, 843.  
 — Breakages of, 743, 847.  
 — Cogging by, 742, 744, 745.  
 — Cost of, 847.  
 — Cranes for, 843.  
 — Double-acting, 742, 842.  
 — Effect of blow by, 742, 840, 841, 843, 853, 854.  
 — for tire ingots, 745, 769.  
 — Forging by, 745, 835, 845, 853.  
 — Foundations for, 880.  
 — Furnaces for, 844, 845.  
 — Handling the ingot at the, 843, 844.  
 — Heavy and light compared, 745, 841.  
 — Objections to, 744, 745, 847, 853.  
 — Output of, 744, 745, 835, 846, 881.  
 — Pallets for, 837, 846.  
 — Porter bar for, 843, 844.  
 — Power of, 742, 745, 841, 842, 843, 847.  
 — Single- and double-acting compared, 842.  
 — Size of, 742, 744, 836, 841, 847, 855.  
 — Special tools for, 769, 835.  
 — Stamping under, 843, 846.  
 — Tilting, 836.  
 — Tup for, 743, 836.  
 — Vibrations caused by, 843, 854, 879.  
**Hand levers**, 636.  
**Handling material** at the hammer, 843.  
 — at the press, 877, 878.  
 — at the reheating furnace, 562-572, 844.  
 — at the rolls, 607, 608, 636, 779, 820.  
 — in the stock yard, 822-825.  
**Handling plates**, 780.  
**Hands**, J., & Sons, Wire bench by, 911.  
**Haniel and Lueg's press**, 869-872.  
**Hannock**, on magnet steel, 420.  
**Harbord**, Analyses during basic Bessemer blow, 194.  
 — — — Siemens melting, 187.  
 — — — of electric furnace steel, 269.

**Harbord**, on Arsenic in steel, 375.  
 — on Carbon in steel, influence on strength, 347.  
 — on impact tests, 323.  
 — on Phosphorus in steel, Effect of, 372.  
 — on polishing micro-sections, 454.  
 — on Talbot process, 203.  
 — on temperature of producer gas, 136.  
 — on Tungsten steel, 417.  
 — on Zinc on steel, Influence of, 378.  
**Harbord and Tucker**, on reheating furnace bottoms, 553.  
**Hardening**, 345, 429.  
 — armour plates, 288.  
 — capacity, Influence of Carbon on, 351.  
 — Carbon, 342.  
 — Carbonless iron, 362.  
 — Case, 247-250.  
 — of steel, 345.  
 — power and Carbon condition, 361.  
**Hardenite**, 464.  
**Hardenite composition** for case-hardening, 249.  
**Hardness**, Calculation of, 321.  
 — Effect of Carbon on, 351.  
 — tests, Brinell, 320.  
**Harmet**, compression of steel ingots, 387, 887.  
**Harrison**, J. H., Boiler experiments, 658.  
**Hartley**, on Bessemer reactions, 79.  
 — on fume, Bessemer converter, 81.  
 — thermo-chemistry of steel processes, 107.  
**Harveyising** armour plates, 284, 286.  
**Haswell**, Welding press by, 875.  
**Hatfield**, on elimination of Silicon in Siemens furnace, 173.  
**Hatton converter**, 71, 72.  
**Hatton**, on Bertrand-Thiel process, 200.  
**Hatton, Hy.**, Table of weights of sheets, 793.  
**Hatton, W.**, Sheet gauge prepared by, 794.  
**Hautefeuille**, on the thermo-chemistry of steel processes, 107.  
**Head**, A. P., on yield of plate mills, 786.  
**Head**, J., on plate mills, 775.  
 — on waste in plate rolling, 781.  
**Hearth**, Making acid Siemens, 158.  
 — Preparing basic Siemens, 183.  
**Heat** absorbed in products of Bessemer blow, 106, 107.  
 — developed during Bessemer blow, 106, 107.  
 — developed in Siemens and similar processes by oxidation, 205-207.  
 — evolution and absorption in Siemens process, 110.  
 — of formation of Carbides, 109.  
 — of formation of compounds, 105.  
 — of formation of slag, 109.  
 — of oxidation of Carbides, 108.  
 — of oxidation of constituents of iron, 106, 108, 109.  
 — Sources of, 655.

**Heat engines**, Theory of, 693.  
**Heat tinting**, Stead's method, 455.  
**Heat treatment of steel**, 428-448.  
 — effect on microstructure, 472-489.  
 — effect of prolonged heating on micro-structure, 486, 487.  
**Heat units**, Definition of, 103.  
**Heath's crucible steel process**, 254.  
**Heathfield's galvanising process**, 920.  
**Heating furnaces**, 844.  
**Heaton process** for removing Sulphur, 191.  
**Helve**, 742.  
**Hematite**, Additions of, in basic process, 103.  
 — pig-iron for acid Bessemer, 230.  
 — — — in basic Siemens, 193, 194.  
 — — — Recarburising Bessemer charge by, 56.  
**Henderson** process for removing Sulphur, 191.  
**Héroult electric process**, 267-269.  
**Heyn's experiments** on heat treatment, 433.  
**Hickman**, A., Ltd., mill, 734.  
**High-speed tool steel**, 414, 416, 425b.  
**Hilgenstock**, on basic Bessemer reactions, 101.  
 — on removal of Sulphur basic Bessemer, 96, 98.  
**Hill**, I., & Sons, Cold saw by, 756, 757.  
**Hills & Jones Co.**, Angle-straightening machine by, 757, 758.  
**Hiorth** electric furnace, 263.  
**Hodgson**, R. B., Wire gauges, 917, 918.  
**Hoerde Works**, 20, 792.  
**Hoesch process**, Chemical changes in, 217.  
 — Production and consumption in, 218.  
**Hoesch Works**, 200a.  
**Holley**, on consumption of fuel in Siemens reheating furnace, 538.  
 — on detachable bottom to converters, 6.  
**Hollingrake**, on fluid compression, 883.  
**Hollis**, Reheating furnace, 546.  
 — Sizes of moulds, 748.  
**Hollow fire**, 835.  
 — shafting, 882.  
**Holsters**. See *Housings*.  
**Holtzer et Cie.**, Chrome steels, 397.  
**Homestead plant**, 1898, 210.  
 — Works, 753.  
 — — — Cogging mill at, 746.  
 — — — Press at, 881, 882.  
 — — — Siemens melting shop at, 1890, 207, 208.  
**Hook boys**, 799.  
**Hoops**, 793, 794, 796.  
**Hot beds**, 653, 763.  
 "Hot saw," 756, 757.  
**Hot working test**, 328.  
**Housings**, 577, 578, 579, 580, 795.  
 — Bad form of, 580.  
 — Changing of, 754.  
 — Daylight in, 580.  
 — for strip mills, 795, 796.

I

Igevsky, on etching micro-sections, 455.  
 Igner plants, Details of, 733.  
 — reversing mill, 734.

Illinois Steel Company, Mill at Joliet, 821.  
 Illumination for microscope, 456-458.  
 Impact tests, 322.  
 Imperial steel, Analysis and properties of, 414.  
 Imperial standard gauge, 917, 918.  
 Indian steel, 292.  
 Indicator, Use of, 669.  
 Induction furnaces, 261-266.  
 Inertia, Influence of, in engines, 667, 668, 669.  
 Ingot cranes, 38, 39, 562.  
 Ingot moulds, 30, 31, 32, 33, 34, 36, 177, 178, 179, 235, 236, 524, 525, 769, 885.  
 — Closed top, 36.  
 — for tires, 177, 178, 179.  
 — Life of, 35.  
 — Teeming of metal into, 30.

**I**ngot stripper, 41-47.  
— Guided, 47, 48.  
**I**ngot stripping, 40.  
**I**ngots, "Bleeding," 548.  
— Boring, 840.  
— Bottom casting of, 35.  
— Bottom *versus* top casting, 37.  
— Cracks in, 392, 393.  
— Crucible steel, 255, 256, 526, 837.  
— Effect of working on, 526.  
— Flaws in, 525, 529, 839.  
— for forgings, 838, 839.  
— Form of, 525, 838.  
— Internal stresses in, 525, 837, 838.  
— Liquation in, 529, 837, 838.  
— Pickling of, 835.  
— Piping in, 386, 524, 838.  
— Reheating of, 840.  
— Rising, stoppering, and wedging down, 56.  
— Size of, 526, 608, 610, 611, 742, 744, 745, 752, 829, 839, 841.  
— Superheating tops of, 838.  
— Top casting of, 30.  
— Topping of, 835.  
— Turner's method of casting, 36, 37.  
— Weight of, 528, 529, 562, 597, 638, 639, 643, 745, 837, 840.  
**I**ngot-tilter, 644.  
**I**ngot tumbler, 570.  
**I**nspecting and testing rails, 764.  
**I**ntensifier, 747, 864, 872, 873, 874, 878.  
**I**odine etching, 455.  
**I**ron, cast, Constitution of, 107, 108.  
— combination with Carbon, 341.  
— Effect of Carbon on properties of, 345, 352.  
— forgings, 840, 841, 843.  
— Heat required for dealing with, 527.  
— making, 526, 527.  
— Occlusion of gases by, 382-386.  
— plates, 782.  
— pure, Production of, in open-hearth furnaces, 195, 196.  
— Rolling of, 526.  
**I**ron Carbide, 342.  
**I**ron Masters' Association, 794.  
**I**ron-nickel alloys, 403.  
**I**ron-oxide, Additions of, in basic process, 103.  
— to Swedish Bessemer, 70.  
— from Oxalate for polishing, 453.  
**I**ron-tin alloys, 377.  
**I**ron-zinc alloys, 378.  
**I**zod, impact test, 322.

**J**

**J**ackson, P. R. & Co., Tire mill by, 769.  
**J**eans, on output of mills, 811.  
**J**enkins' formula for efficiency of producers, 131-133.  
— on temperature variations in producer gas, 136.

**J**essop steel, 425b.  
**J**essop & Sons, gas-fired crucible furnace, 258.  
**J**essops, Harmet's process at, 888.  
**J**ib crane, 843.  
**J**ohnson, R., & Nephew, Wire rolling at, 801.  
**J**oists, 610, 612, 613, 635, 756, 822.  
**J**oilet Works, 805, 821.  
**J**ones, Capt., method of fluid compression, 888.  
**J**ones, H. J., on armour plates, 284, 288.  
**J**ones & Laughlin's, Talbot process, 202.  
**J**ones & Laughlin's Works, 814.  
**J**ordan, on Bessemer reactions, 79, 86.  
**J**ulian, on Bessemer reactions, 79.  
"Jumping," 845, 901.  
**J**urievka Works, Basic open hearth practice at, 221, 222, 223.

**K**

**K**arsten, on Carbon and iron, 342.  
**K**eller electric process, 270, 271.  
**K**ennedy, J., Design of mill, 786.  
**K**erpely producer, 127, 128.  
**K**essler, Analyses of Bessemer metal, 90.  
**K**illing of crucible steel, 257.  
**K**irkaldy, on impact test, 322, 323.  
— on shape of test piece, 311, 312.  
— on test of Kirkstall bar, 762.  
**K**irkham reversing valve, 150, 152.  
**K**irkstall bars, 762.  
**K**jellin electric process, 261, 262.  
**K**ladno, Bertrand-Thiel process at, 200.  
**K**oerting engine, 710.  
**K**oettgen, C., mill power, 734.  
**K**raus, M., on distribution of heat in reheating furnace, 558.  
**K**refeld Steel Works, mill, 799, 800.  
**K**rupp, carburising armour plate, 286, 290.  
— depophosphorising process, 197.  
— Fluid compression by, 888.  
— Large crucible ingots by, 837.  
**K**rupp-Harveyised plates, 286.

**L**

**L**abour, Cost of, 805, 830, 831, 832.  
**L**adle stoppers, Running, 56.  
**L**adies, Caspersson's converter, 70.  
— Casting, 164, 165.  
— Details of, 24, 25, 26, 27, 28.  
— Hot metal, 21, 22, 23.  
— Receiving, 52.  
— for Siemens furnace, 164.  
— for straight Siemens pit, 165.  
— Tipping, 21, 22, 23.  
**L**amberton, Messrs., Plate shears by, 781.

**L**ancashire boiler, 661.  
**L**angley, on diffusion of Carbon, 246.  
**L**anty, M., on German reheating furnaces, 547.  
— on loss in soaking pits, 551.  
**L**ap-welded tubes, 899, 900.  
**L**athe, 619, 846, 847, 849, 850, 851.  
"Latteins," 794.  
**L**auth plate mill, 597, 630, 713, 784, 785.  
**L**aw, on oxygen in steel, 386.  
Laying out the mill, 527, 826-829.  
**L**ead, Coating steel with, 932.  
**L**eading spindle, 590.  
**L**eather, Charred, for case-hardening, 249.  
**L**e Chatelier, on critical points, 353.  
— etching microsections, 455.  
— polishing microsections, 453, 454.  
— preparation of polishing powders, 452, 453.  
— pyrometer, 440.  
— Sulphides in steel, 371.  
**L**edejür, on Bessemer reactions, 79.  
— forging presses, 881.  
— hardening Carbon, 343.  
— temper Carbon, 343.  
**L**ewis Forge, Prices of plates, 782.  
**L**encachez, Basic lining, 58.  
Lengths rolled, 811, 821, 822.  
**L**e Play, on cementation of iron, 341.  
**L**evers, 636, 637, 638, 644, 650.  
**L**evy, on Manganese Sulphide, 371.  
**L**ifting tables, 597, 641, 642, 643, 644, 770, 829.  
**L**ifts, 638, 639, 829.  
**L**illeshall Co., Mill, 752, 758.  
**L**imberg, Use of blast-furnace gas, 715.  
**L**ime as a basic material, 184.  
— for basic Bessemer, 65, 92, 93.  
— for basic linings, 58, 61.  
— Use of, in gas producers, 175.  
**L**imestone, Witkowitz, Analyses of, 62.  
**L**ining basic Bessemer converter, 59.  
— Siemens furnace, 182.  
— converters, 8.  
— Materials for, 13.  
"Lining up the mill," 579.  
**L**iquation, 378-381, 529, 837, 838.  
**L**ive rollers, 639, 641, 643, 651, 746, 778, 779, 784.  
**L**loyd, F. H., & Co., Pinions by, 589, 590.  
**L**oad factor, 736.  
**L**oading up material, 753, 760, 762, 778, 796, 822, 824.  
**L**oam sand, Analysis of, 235.  
**L**ooping mill, 595, 599, 797, 798.  
**L**osses in basic Bessemer, 102.  
— in soaking pits, 551.  
**L**owea Engineering Co., 563.  
**L**ukens Iron and Steel Co., Mills at, 784.  
**L**urmann, Blast-furnace gas for engines, 698.  
**L**ysaght, J., & Co., on the influence of Zinc on steel, 378.  
— Normanby Park plant, 470.

**M**

**M**cCance, theory of hardening, 364.  
**M**'Keesport Tin Plate Company, Mill at, 927.  
**M**'Kenna process for re-rolling rails, 768.  
**M**'William, on diffusion of Carbon in steel, 246.  
— on elimination of Silicon in Siemens furnace, 173.  
**M**achine for galvanising, 921, 922, 923.  
— for testing springs, 337.  
— tools, 847, 848, 849, 850.  
**M**ackintosh, Hemphill & Co., Mill by, 746.  
**M**aemillan, on size of regenerators, 146.  
**M**ærz port, 144, 145.  
**M**agnesite, Analysis of, 233.  
— bricks for basic Siemens, 183, 184.  
**M**agnesium, Effect of, on nickel, 404.  
**M**agnet steel, 420.  
**M**agnetic oxide of iron, Formation of, in converter, 82.  
**M**agnetic properties, Effect of Carbon on, 351.  
— Silicon on, 369.  
— of nickel steel, 409.  
— of Tungsten steel, 415, 420.  
**M**anganese additions, basic Bessemer, 101, 102.  
— Bessemer process, 55.  
— Swedish Bessemer, 69.  
— Effect of, in removing Sulphur in basic Siemens, 190, 191.  
— Influence of, on steel, 374.  
— in presence of Sulphur, 370.  
— — in Swedish Bessemer, 69.  
— Rapid determination of, 522.  
— in Siemens process, 163, 168.  
— in steel castings, 234, 235.  
**M**anganese and high Carbon steel, 375.  
— and Silicon in Bessemer converter, 83, 86, 88.  
**M**anganese steel, 399-403.  
**M**anipulators for ingots, 644, 746.  
**M**annaberg, Analysis of Talbot producer gas, 134.  
**M**annesmann process, 908.  
**M**arshall, Fleming & Jack, Crane by, 166.  
**M**artens, on etching microsections, 455.  
— on microscopical examination of steel, 449.  
— on polishing microsections, 450.  
**M**artensite, 463.  
**M**artin, E. P., on the basic process, 59.  
**M**artin, P. & E., use of scrap, 140a.  
**M**ass action in converter, 82.  
**M**assenez, on desulphurisation in metal mixer, 20, 191.  
**M**assey, B. & S., Tilting hammer by, 836.  
**M**athot, Prof., on gas engines, 712.  
**M**aximum stress, 298.  
**M**easurement of test bar, Details of, 315, 316.  
**M**echanical chargers for Siemens furnace, 160.

**Mechanical chargers**, Broadbent, 163.  
 — Wellman, 161.  
 — Wellman-Seaver, 162.  
**Mechanical feed** for producers, 120, 129, 130.  
 — **gas producers**, 124-128.  
   — Hughes, 126, 127.  
   — Kerpely, 127, 128.  
   — Rehmann, 128.  
   — Talbot, 124-126.  
   — means for preventing blowholes, 891, 892.  
   — stokers, 657.  
   — work, Need for, 523.  
**Melting** crucible steel, 255.  
 — heat, 245.  
 — hole, 251.  
**Melting points** of metals, 441.  
**Melting shop**, open hearth, Arrangement of, 207-212.  
**Mender**, 167.  
**Menelaus**, on the Dowlais mill, 627.  
**Merchant mill**, 728, 758, 759, 820.  
**Metal mixer**, 15, 16, 17, 18.  
 — modern type, 21.  
 — Reactions in, 19, 20.  
 — Removal of Sulphur in, 20, 191.  
**Metalloids**, Heat developed by oxidation of, in Siemens, 205-207.  
 — Removal of, in basic Siemens, 186, 187.  
   — Bertrand-Thiel process, 198.  
   — Talbot continuous process, 200.  
 — State of combination of, in iron, 107.  
**Metcalf**, on compression results, 350.  
 — on tempering colours, 345.  
**Metcalf and Langley**, Diffusion of Carbon, 246.  
**Methane**, Calorific power of, 131.  
 — for case-hardening, 250.  
 — Specific heat of, 132.  
 — in steel, 384.  
**Micro-constituents** of steel, 461, 466.  
 — Austenite, 464.  
 — Cementite, 462.  
 — Ferrite, 461.  
 — Hardenite, 464.  
 — Martensite, 463.  
 — Pearlite, 463.  
 — Osmondite, 464.  
 — Sorbite, 464.  
 — Troostite, 464.  
**Micrometer calipers**, 313.  
**Microscopic** accessories, 459.  
 — apparatus, 456-459.  
 — examination, 459-461.  
 — Sampling for, 466.  
**Microscopical composition** of quenched steels, 466.  
 — of unhardened Carbon steels, 465.  
**Micro-sections**, Etching of, 454-456.  
 — Polishing of, 449-454.  
 — Preparation of, 449.  
**Microstructure**, Development of, 454-456.  
 — Examination for, 461.

**Microstructure**, of cement bar, 244.  
 — of copper-silver alloys, 358.  
 — of iron-Carbon alloys, 358.  
 — Photographs of, 358, 461-464, 468, 472-490.  
**Mill**, Bedding of, 579.  
 — compared with steam hammer, 600, 742, 744, 745, 834, 854.  
 — Details of, 573, *et seq.*  
 — Development of, 528, 529, 539, 600, 797.  
 — Early rolling, 526, 600.  
 — Five leading types of, 595.  
 — Laying out the, 527, 826-829.  
 — "Lining up" the, 579.  
 — Outputs of. See *Outputs of rolling mills*.  
 — Speed of, 607, 672.  
 — Types of, automatic, 805, 808, 821.  
   — bar, 758, 759, 819, 820.  
   — Bedson's, 598, 801, 802, 811.  
   — Belgian, 631, 797, 798, 799.  
   — billet, 752, 753, 754, 814.  
   — blooming, 578, 598, 609, 610, 610, 611, 638, 639, 742, 743, 744, 744, 745, 751.  
   — Boecker's, 805, 806.  
   — breaking down, 808, 809.  
   — Brown's, 629.  
   — cogging, 578, 598, 609, 610, 611, 638, 639, 742, 743, 744, 745, 751.  
   — combination, 808.  
   — common, 742, *et seq.*  
   — continuous, 595, 598, 607, 801, 804, 811, 814, 815, 817, 818, 819.  
   — "Dowlais," 627, 799.  
   — English rail, 762.  
   — Five leading types of, 595.  
   — Garrett's, 803, 804, 805, 811.  
   — Gray's, 634.  
   — Guide for, 591, 592, 593, 594, 728, 729, 760, 802, 808, 816.  
   — lap-welding tube, 900.  
   — Lauth's, 597, 630, 713, 784, 785.  
   — looping, 595, 599, 797, 798.  
   — merchant, 728, 758, 759, 820.  
   — plate. See *Plate mill*.  
   — pull-over, 595, 596, 608, 759, 762, 763.  
   — rail, 742, 762, 764, 827, 830, 833.  
   — reciprocal, 629.  
   — reversing, 595, 598, 627, 644, 730, 731, 774, 776, 827, 828.  
   — rod, 608, 797, 801, 802, 805.  
   — Sack's, 634.  
   — section, 756.  
   — sheet, 596, 787, 790.  
   — slabbing, 747, 778, 784, 785.  
   — special, 627.  
   — strip, 794, 795, 814.  
   — three-high. See *Three-high mill*.  
   — tire, 768-773.

**N**

Nasmyth, on suggested reversing mill, 598.  
**National Steel Co.**, Mills, 821.  
**Native forge or bloomery**, Production of steel in, 291.  
**Natural gas**, 139.  
**Neck brasses**, Adjustment of, 581, 582, 583, 584, 585, 586.  
 — pinions, 588, 589, 590, 591, 596, 597, 628, 630, 786.  
**Neilson, R. M.**, on superheating, 663.  
**New form Siemens furnace**, 258-260.  
 — — — reheating furnace, 541.  
 — — — vertical underground reheating furnace, 552.  
**Niagra Co.**, Voltage, 722.  
**Nickel**, Properties of, 403, 404.  
**Nickel-Chrome steels**, 284, 410.  
**Nickel-iron alloys**, 403.  
**Nickel steel**, 405-411.  
 — Magnetic properties of, 409.  
 — Mechanical properties of, 405-407.  
 — Segregation in, 380.  
 — wire, 409.  
**Nitrate of Soda** as a desulphurising agent, 191.  
**Nitric acid etching**, 454.  
**Nitrides of iron**, 383.  
**Nitrogen** in steel, 382, 383.  
 — Specific heat of, 132.  
**Normanby Park Steel Works**, 470.  
**North-Eastern Works**, Bessemer plant, 470.  
 — — — shop, 51.  
**Nozzle of casting ladle**, 26, 28.  
**Nurnberg gas engine**, 704.  
**Nykoppa Works**, Revolving moulds at, 892.

**O**

**Occlusion of gases** by iron and steel, 382-386.  
 — Effect of Aluminium on, 394.  
 — Vanadium on, 422.  
**Odelstjerna**, on position of ports, 142.  
**Oechelhäuser engine**, 708.  
**Oehler Works**, Electric current at, 271.  
**Ohio Steel Works**, Mill, 766.  
**Oil quenching**, 437.  
**Oil-tempered axle steel**, Photo-micrograph of, 488.  
**Olefiant gas**, Calorific power of, 131.  
 — Specific heat of, 132.  
**Oleson & Weiffenback**; on case-hardening, 250.  
**Open hearth furnace**, Making hearth and tapping hole in, 158.  
 — Charging and starting, 159.  
**Open hearth melting shop**, Arrangement of, 207-212.  
**Open hearth plant**, Bethlen Falva, 211.  
 — Georgsmarienhütte, 212.